



**MADE EASY**

Leading Institute for IES, GATE & PSUs

Delhi | Bhopal | Hyderabad | Jaipur | Pune

Web: [www.madeeasy.in](http://www.madeeasy.in) | E-mail: [info@madeeasy.in](mailto:info@madeeasy.in) | Ph: 011-45124612

**DC MACHINE + TRANSFORMER  
+ INDUCTION**

**ELECTRICAL ENGINEERING**


**Date of Test : 08/07/2026**

**ANSWER KEY >**

- |        |         |         |         |         |
|--------|---------|---------|---------|---------|
| 1. (d) | 7. (b)  | 13. (b) | 19. (b) | 25. (a) |
| 2. (a) | 8. (d)  | 14. (a) | 20. (d) | 26. (d) |
| 3. (a) | 9. (b)  | 15. (b) | 21. (a) | 27. (a) |
| 4. (d) | 10. (d) | 16. (b) | 22. (c) | 28. (a) |
| 5. (c) | 11. (c) | 17. (c) | 23. (c) | 29. (d) |
| 6. (d) | 12. (d) | 18. (b) | 24. (b) | 30. (a) |

**DETAILED EXPLANATIONS**

1. (d)



$$V_H = 132 \text{ V}$$

The maximum volt-ampere rating in either winding of this transformer is 100 VA.

The voltage on series winding is 12 V

$$I_{\text{series, max}} = \frac{S_{\text{max}}}{V_{\text{series}}} = \frac{100}{12} = 8.33 \text{ A}$$

Since  $I_{\text{series}}$  is equal to  $I_H$ , so secondary apparent power is

$$S_{\text{out}} = V_S I_S = V_H I_H = 132 \times 8.33 = 1100 \text{ VA}$$

2. (a)

Maximum efficiency occurs at unity power factor and when copper loss is equal to the iron loss kVA rating at maximum efficiency

$$S_m = S_{fl} \sqrt{\frac{P_i}{P_{cu}}} = 300 \times \sqrt{\frac{1.5}{4.5}} = 173.205 \text{ kVA}$$

$$\therefore \text{Maximum efficiency} = \frac{\text{Power output}}{\text{Power output} + \text{losses}}$$

$$\% \eta_{\text{max}} = \frac{173.205}{173.205 + 1.5 + 1.5} \times 100 = 98.29\%$$

3. (a)

$$\text{Power output, } P_0 = 10 \text{ kW}$$

$$\text{Frequency, } f = 50 \text{ Hz}$$

$$\text{Poles, } P = 6$$

$$\text{Slip, } S = 0.04$$

$$\text{Friction and windage losses} = 0.4 \text{ kW}$$

$$\text{Mechanical power developed} = 10.4 \text{ kW}$$

$$\text{Air gap power, } P_g = \frac{\text{Mechanical power developed}}{1 - s} = \frac{10.4}{1 - 0.04} = 10.83 \text{ kW}$$

$$\text{Synchronous speed} = \frac{120 \times 50}{6} = 1000 \text{ rpm or } 104.72 \text{ rad/sec}$$

Full load electromagnetic torque,

$$T_e = \frac{P_g}{\omega_s} = \frac{10.83 \times 10^3}{104.72} = 103.42 \text{ N-m}$$

4. (d)

$$\text{Hysteresis loss } P_h \propto fB^x \propto f\left(\frac{V}{f}\right)^x$$

$$\frac{P_{h1}}{P_{h2}} = \frac{f_1 \left(\frac{V_1}{V_2} \times \frac{f_2}{f_1}\right)^x}{f_2 \left(\frac{V_1}{V_2} \times \frac{f_2}{f_1}\right)^x}$$

$$\frac{700}{P_{h2}} = \frac{50 \left(\frac{1000}{2000} \times \frac{100}{50}\right)^x}{100 \left(\frac{1000}{2000} \times \frac{100}{50}\right)^x}$$

$$P_{h2} = \frac{700 \times 100}{50} = 1400 \text{ W}$$

Eddy current loss,

$$P_e \propto B^2 f^2 \propto f^2 \left(\frac{V}{f}\right)^2$$

$$\frac{P_{e1}}{P_{e2}} = \left(\frac{f_1}{f_2}\right)^2 \left(\frac{V_1}{V_2} \times \frac{f_2}{f_1}\right)^2$$

$$\frac{300}{P_{e2}} = \left(\frac{50}{100}\right)^2 \left(\frac{1000 \times 100}{2000 \times 50}\right)^2$$

$$P_{e2} = 1200 \text{ W}$$

$$\text{Total core loss, } P_c = P_{h2} + P_{e2} = 1400 + 1200 = 2600 \text{ W}$$

5. (c)

We know that,

$$\text{Torque, } T \propto \phi I_a$$

$$\text{So, } \frac{T_1}{T_2} = \frac{\phi_1 I_{a1}}{\phi_2 I_{a2}}$$

$$T_2 = \frac{\phi_2 I_{a2}}{\phi_1 I_{a1}} \times T_1$$

$$\phi_2 = 1.2 \phi_1, I_{a1} = 40 \text{ A}, I_{a2} = 60 \text{ A}$$

$$T_2 = 1.2 \times \frac{60}{40} \times 20 = 36 \text{ N-m}$$

6. (d)

$$\frac{T_{st}}{T_{fl}} = \left(\frac{I_{st}}{I_{fl}}\right)^2 s_{fl}$$

$$\text{For } T_{st} = T_{fl}$$

$$\frac{I_{st}}{I_{fl}} = \sqrt{\frac{1}{s_{fl}}} = \frac{1}{\sqrt{0.01}} = 10$$

7. (b)

$$\text{Rotation speed} = 600 \text{ rpm}$$

$$N = \frac{600}{60} = 10 \text{ rev/sec}$$

Peripheral velocity of commutator,

$$V_p = \pi DN = \pi \times 50 \times 10 \text{ cm/sec}$$

As we know,

$$V_p \times t_c = \text{Brush width}$$

$$\therefore \text{Time of commutation, } t_c = \frac{2}{\pi \times 50 \times 10} = 1.273 \text{ msec}$$

8. (d)

We know that, emf generated,

$$E = \frac{P\phi NZ}{60A} = \phi \times 50 \times 18 \times \frac{9000}{60} \times \frac{4}{2}$$

$$357 = \phi \times 50 \times 18 \times \frac{9000}{60} \times \frac{4}{2}$$

Flux per pole,  $\phi = 1.32 \text{ mWb}$

9. (b)

Field current,  $I_f = \frac{250}{125} = 2 \text{ A}$

No load armature current,  $I_{a0} = 16 - 2 = 14 \text{ A};$

Constant losses,  $P_K = (250 \times 14 - (14)^2 \times 0.2) + 250 \times 2 = 3960.8 \text{ W}$

$$I_a = 152 - 2 = 150 \text{ A}$$

$$P_L = I_a^2 R_a + P_K = (150)^2 \times 0.2 + 3960.8 = 8.461 \text{ kW}$$

$$P_{in} = 250 \times 152 = 38 \text{ kW}$$

$$\therefore \text{Efficiency, } \eta_n = \frac{38 - 8.461}{38} \times 100 = 77.73\%$$

10. (d)

For dc series motor;

Given,  $V_t = 220 \text{ V},$   
 $N_r = 1500 \text{ rpm}$   
 $I_a = 25 \text{ A},$   
 $R_a = 0.4 \Omega,$   
 $R_{se} = 0.6 \Omega$

Torque;  $T \propto I_a^2$

back emf at 1500 rpm,

$$E_{b1} = V_t - I_{a1} (R_a + R_{se}) = 220 - 25 (0.4 + 0.6)$$

$$E_{b1} = 195 \text{ V}$$

We know that,  $E_b \propto N$

Back emf at 1200 rpm;

$$\frac{E_{b2}}{195} = \frac{1200}{1500}$$

$$E_{b2} = \frac{12}{15} \times 195 = 156 \text{ V}$$

Let us assume  $R_{ext}$  to be connected in series:

$$E_{b2} = V_t - I_{a2} (R_a + R_{se} + R_{ext})$$

To obtain rated torque at 1200 rpm, armature current must be same;

i.e.  $I_{a2} = 25 \text{ A}$

Now,  $156 = 220 - 25 (0.4 + 0.6 + R_{ext})$

$$220 - 156 = 25 (1 + R_{ext})$$


$$R_{ext} = 1.56 \Omega$$

11. (c)

The apparent power rating will be

$$S_{\text{auto}} = \frac{N_{\text{series}} + N_{\text{common}}}{N_{\text{series}}} S_{TW}$$

$$= \frac{1.2 + 12}{1.2} \times 1000 = 11000 \text{ KVA}$$



The transformer impedance in p.u. system when connected in two winding manner is,

$$Z_{\text{eq}} = (0.01 + j0.08) \text{ p.u.}$$

The apparent power advantage of this auto transformer is 11, so the per unit impedance of the auto transformer is,

$$Z_{\text{eq}} = \frac{0.01 + j0.08}{11} = (0.00091 + j0.00727) \text{ p.u.}$$

12. (d)

$$I_A = I_L - I_F = 200 - \frac{250}{50} = 195 \text{ A}$$

$$E_A = V_T - I_A R_A = 250 - (195 \times 0.06) = 238.3 \text{ V}$$

At  $I_L = 200 \text{ A}$ , the demagnetizing mmf is 840 A.T. So, effective shunt field current of the motor is

$$I_F^* = I_F - \frac{\text{mmf}}{N_F} = 5 - \frac{840}{1200} = 4.3 \text{ A}$$

From the given graph, if  $I_F^* = 4.3 \text{ A}$  then  $E_{\text{no load}} = 233 \text{ V}$ 

$$\frac{E_{1NL}}{E_2} = \frac{N_{1NL}}{N_2}$$

$$\frac{233}{238.3} = \frac{1200}{N_2}$$

Speed of the motor,  $N = 1227.3 \text{ rpm}$ 

13. (b)

Given,

$$I_{\text{st}} = 6 \times I_{fL}$$

$$I_{fL} = \frac{\text{Power in kVA}}{\sqrt{3} \times V_L} = \frac{50 \times 10^3}{\sqrt{3} \times 440} = 65.608 \text{ A}$$

Current drawn by auto transformer from the mains at starting,

$$I_{\text{st}} = x^2 I_{\text{st}(\text{motor})} = x^2 \times 6 \times I_{fL} = (0.5)^2 \times 6 \times 65.608 = 98.412 \text{ A}$$

Starting kVA drawn by the auto transformer

$$= \sqrt{3} V_L I_{\text{st}(\text{auto})} = \sqrt{3} \times 440 \times 98.412 = 75 \text{ kVA}$$

14. (a)

We know that,

$$\text{Torque, } T = \frac{3}{\omega_{sm}} \times \frac{V^2}{R_2'} s \text{ (for low slip)}$$

Now,  $T = \text{constant}$        $T \propto V^2 s$

(or)                       $V_2^2 s_2 = V_1^2 s_1$

(or)                       $s_2 = \left(\frac{V_1}{V_2}\right)^2 s_1$

(or)                       $s_2 = 4s_1,$

hence slip increases 4 times,

Also,                       $T = \frac{3I_2'^2}{\omega_{sm}} \times \frac{R_2'}{s} = \text{const.}$

(or)                       $I_2'^2 \propto s$

$$\frac{I_2'}{I_1'} = \sqrt{\frac{s_2}{s_1}} = \sqrt{\frac{4}{1}} = 2$$

Hence, current increases by 2 times.

**15. (b)**

The motor and generator are identical

DC supply given to motor,

$$V = 1 \text{ p.u.}$$

Current in both motor and generator

$$I_{am} = I_{ag} = 1 \text{ p.u.}$$

$$R_{am} = R_{ag} = 0.02 \text{ p.u.}$$

Back emf in motor,  $E_m = V - I_{am} R_{am}$

$$E_m = 1 - 1 \times 0.02 = 0.98 \text{ p.u.}$$

Also

$$E_m I_{am} = E_g I_{ag}$$

$\Rightarrow$                        $E_m = E_g = 0.98 \text{ p.u.}$

Terminal voltage of generator,  $V_g = E_g - I_{ag} \cdot R_{ag} = 0.98 - 1 \times 0.02 = 0.96 \text{ p.u.}$

$$\text{Load resistance} = \frac{V_g}{I_{ag}} = \frac{0.96}{1.0} = 0.96 \text{ p.u.}$$

**16. (b)**

$$\text{Synchronous speed, } N_s = \frac{120 \times 50}{6} = 1000 \text{ rpm}$$

$$\text{Stalling speed} = 900 \text{ rpm}$$

$$\text{Slip at stalling torque, } s = \frac{1000 - 900}{1000} = 0.1$$

Slip at maximum torque;       $S_{mT} = \frac{R_2}{X_2} = \frac{0.01}{X_2}$

$\therefore$                        $0.1 = \frac{0.01}{X_2}$   
 $X_2 = 0.1 \Omega$

To obtain maximum torque at starting,

Let rotor resistance =  $R_2'$

At starting,                      slip,  $s = 1$

$$S_{mT} = \frac{R'_2}{X_2}$$

$$\Rightarrow 1 = \frac{R'_2}{0.1}$$

$$\Rightarrow R'_2 = 0.1 \text{ } \Omega/\text{phase}$$

The external resistance to be added,

$$R_{\text{ext}} = 0.1 - 0.01 = 0.09 \text{ } \Omega/\text{phase}$$

17. (c)

For maximum torque ( $T_{\text{max}}$ )

$$s_{\text{max}, T} = \frac{R_2}{X_2}$$

$$s_{\text{max}, T} = \frac{1}{4}$$

$$\text{Synchronous speed, } N_s = \frac{120 \times 50}{6} = 1000 \text{ rpm}$$

Now at  $T_{\text{max}}$  speed of motor,

$$N_r = (1 - s) N_s = (1 - 0.25) \times 1000$$

$$N_r = 750 \text{ rpm}$$

18. (b)

Given that,

$$V_{OC} = 230 \text{ V,}$$

$$I_{OC} = 1.3 \text{ A,}$$

$$P_{OC} = 100 \text{ W}$$

$$R_C = \frac{V_{OC}^2}{P_{OC}} = \frac{230^2}{100} = 529 \text{ } \Omega$$

Power factor angle,

$$\phi_{OC} = \cos^{-1} \left( \frac{P_{OC}}{V_{OC} I_{OC}} \right) = \cos^{-1} \left( \frac{100}{230 \times 1.3} \right) = 70.46^\circ$$

$$X_\phi = \frac{R_C}{\tan \phi_{OC}} = \frac{529}{\tan 70.46^\circ} = 187.73 \text{ } \Omega$$

Referred to high voltage side,

$$R_C = 529 \times \left( \frac{400}{230} \right)^2 = 1600 \text{ } \Omega$$

$$X_\phi = 187.73 \times \left( \frac{400}{230} \right)^2 = 567.8 \text{ } \Omega$$

19. (b)

Load characteristic is

$$T_L \propto N^2$$

For dc series motor, torque-current relation is given by


$$T_d \propto I_a^2$$

$$\therefore \frac{I_{a2}}{I_{a1}} = \frac{N_2}{N_1}$$

$$\frac{I_{a2}}{15} = \frac{750}{1500}$$

$$I_{a2} = 7.5 \text{ A}$$

**Case-I:**



$$E_{a1} = 200 - 15 \times (0.03 + 0.05)$$

$$E_{a1} = 198.8 \text{ V}$$

**Case-II:**

When additional resistance added in series with the armature circuit,

$$I_{a2} = 7.5 \text{ A,}$$

$$N_2 = 750 \text{ rpm}$$

Now,

$$E_a \propto \phi \omega_m$$

$$\frac{E_{a2}}{E_{a1}} = \frac{N_2 I_{a2}}{N_1 I_{a1}} \quad (\text{In dc series motor } \phi \propto I_a)$$

$$\frac{E_{a2}}{198.8} = \frac{750 \times 7.5}{1500 \times 15}$$


$$E_{a2} = 49.7 \text{ V}$$

$$E_{a2} = 200 - 7.5(0.08 + R_{\text{ext}}) = 49.7$$

$$0.08 + R_{\text{ext}} = \frac{200 - 49.7}{7.5}$$

$$R_{\text{ext}} = 20.04 - 0.08 = 19.96 \text{ } \Omega$$

20. (d)



EMF per turn is constant on either side of transformer. Total voltage rating of secondary side of transformer = 24 V. So, 24 turns will be required with center tap.

21. (a)

As we know,

$$\frac{V_1}{V_2} = \frac{N_1}{N_2} \Rightarrow V_2 = \frac{1}{5} \times 230 = 46 \text{ V}$$

$$I_s = \frac{V_2}{R_2} = \frac{46}{4} = 11.5 \text{ A}$$

So,

$$I_p = I_s \frac{N_2}{N_1} = \frac{11.5}{5} = 2.3 \text{ A}$$

22. (c)  
Case-I


$$r_2 = 0.2 \Omega,$$

$$X_2 = 2 \Omega,$$

$$E_2 = 60 \text{ V}$$

Impedance,  $Z_2 = (0.2 + j0.04 \times 2) = 0.2154 \angle 21.89^\circ \Omega$

$$s = \frac{1500 - 1440}{1500} = 0.04$$




$\therefore P_{ag} = |sE_2'| |I_2'| \cos \theta_2$

$$= (0.04 \times 60) \times 11.14 \times \cos(21.8) \quad \dots(i)$$

Case-II

$$s' = \frac{1500 - 1800}{1500} = -\frac{1}{5}$$

Impedance,  $Z_2' = \left( 0.2 - j2 \times \frac{1}{5} \right) = 0.447 \angle -63.43^\circ \Omega$



$$P_{ag}' = (s \times 60 + E_2') \times I_2' \cos \theta_2' \quad \dots(ii)$$

$$I_2' = \frac{(s' \times 60 + E_2')}{\sqrt{r_2'^2 + (s'x_2)^2}} = \frac{\left( -\frac{1}{12} + E_2' \right)}{0.4472}$$

From equation (ii),

$$\therefore P_{ag}' = (-12 + E_2') \cdot \frac{(-12 + E_2')}{0.4472} \times 0.4472$$

Since torque is same for both cases

$$\therefore P_{ag} = P_{ag}'$$

$$(-12 + E_2')^2 = 24.84$$

$$E_2' = 16.98 \text{ V}$$

23. (c)

Starting current drawn by motor rated voltage =  $I_{SC}$

When supply voltage is reduced by factor 'x',

$$\text{then starting current drawn by motor} = \frac{x \cdot V_{\text{rated}}}{Z_{sc}} = xI_{sc}$$

Since autotransformers transformation ratio is 1 : x

So starting current drawn from supply by transformer is =  $x^2 I_{SC}$

it is also given that,  $I_{SC} = 6 I_{fl}$

$$I_{fl} = \frac{50000}{\sqrt{3} \times 440} = 62.60 \text{ A}$$

Starting kVA drawn by auto transformer

$$(\text{kVA})_{\text{startor}} = \sqrt{3} V_L I_{L(\text{starting})} = \sqrt{3} V_L x^2 I_{SC} = \sqrt{3} V_L x^2 6 \times I_{fl}$$

$$= \sqrt{3} \times 440 \times \frac{1}{4} \times 6 \times 65.60 = 75 \text{ kVA}$$

24. (b)

From the given condition,

$$I_{\max}^2 r_2' = 18 I_{fL}^2 r_2'$$

$$\left( \frac{I_{fL}}{I_{\max}} \right)^2 = \frac{1}{18}$$

As we know, 
$$\frac{T_{fL}}{T_{\max}} = \frac{2 \cdot s_{mT} s_{fL}}{s_{m,T}^2 + s_{fL}^2} \quad \dots(i)$$

Also, 
$$\frac{T_{fL}}{T_{\max}} = \left( \frac{I_{fL}}{I_{\max}} \right)^2 \times \frac{s_{m,T}}{s_{fL}} \quad \dots(ii)$$

From equation (i) and (ii),

$$\left( \frac{I_{fL}}{I_{\max}} \right)^2 = \frac{2s_{fL}^2}{s_{m,T}^2 + s_{fL}^2}$$

$$\frac{1}{18} = \frac{2}{\left( \frac{s_{m,T}}{s_{fL}} \right)^2 + 1}$$

$$\Rightarrow s_{m,T} = s_{fL} \sqrt{35} = 0.025 \times \sqrt{35} = 0.1479 \approx 0.15$$

25. (a)

$$\eta_{2\text{-wdg}} = \frac{10 \times 0.85}{10 \times 0.85 + P_L} = 0.95$$


$$P_L = 0.4473 \text{ kW}$$

$$I_1 = \frac{10000}{400} = 25 \text{ A}$$

$$I_2 = \frac{10000}{100} = 100 \text{ A}$$

$$(\text{kVA})_{\text{auto}} = 500 \times 100 = 50 \text{ kVA}$$

$$\eta_{\text{auto}} = \frac{(\text{kVA})_{\text{auto}} \cdot \cos \phi}{(\text{kVA})_{\text{auto}} \cdot \cos \phi + P_L} = \frac{50 \times 0.95}{50 \times 0.95 + 0.4473} = 0.9906 = 99.06\%$$



26. (d)

Total armature resistance =  $R_{am}$

$R_{am}$  = (armature winding + interpolar winding + brush) resistance

$$R_{am} = 0.2 + 0.1 + 0.1 = 0.4 \Omega$$

$$R_f = 100 \Omega$$

$$I_{f1} = \frac{V}{R_f} = \frac{220}{100} = 2.2 \text{ A}$$

$$E_{a1} = V - (I_L - I_f) R_{am} = 220 - (200 - 2.2) \times 0.4 = 140.88 \text{ V}$$

As we know,

$$E_a \propto N \phi$$

$$\frac{E_{a2}}{E_{a1}} = \frac{N_2 I_{f2}}{N_1 I_{f1}} \quad (\phi \propto I_f)$$

$$\frac{220 - 0.4(200 - I_{f2})}{140.88} = \frac{1600 I_{f2}}{1200 \times 2.2}$$

$$220 - 80 + 0.4 I_{f2} = 85.38 I_{f2}$$

$$I_{f2} = \frac{140}{84.98} = 1.6474 \text{ A}$$

$$I_f = \frac{V}{100 + R_{\text{ext}}}$$

$$\Rightarrow R_{\text{ext}} = \frac{220}{1.6474} - 100 = 33.54 \text{ } \Omega$$

27. (a)

As we know,

$$E_a = \frac{ZNP\phi}{60A} = \frac{ZN\phi}{60} \left( \frac{P}{A} \right)$$

$$= \frac{944 \times N \times 34.6 \times 10^{-3}}{60} \times 2 \quad \text{for wave connected } A = 2,$$

$$E_a = 1.088 N \quad \dots(i)$$

and  $E_a I_a = 4 \times 10^3 \quad \dots(ii)$

$$I_a = \frac{V - E_a}{R_a} = \frac{500 - E_a}{3} \quad \dots(iii)$$

$$4000 = \frac{500E_a - E_a^2}{3}$$

On putting equation (ii) in equation (iii),

$$4000 = \frac{500E_a - E_a^2}{3}$$

$$E_a^2 - 500E_a + 12000 = 0$$

On solving for  $E_a$ ,

$$E_a = 474.72 \text{ V}, 25.27 \text{ (neglected due to efficiency consideration)}$$

So,

$$N = \frac{E_a}{1.088} = \frac{474.72}{1.088} = 436.32 \text{ rpm}$$

28. (a)

At no load;

$$\text{Back emf, } E_{b0} = V_t - I_{a0} (R_a)$$

$$E_{b0} = 220 - 3(0.5)$$

$$E_{b0} = 218.5 \text{ V}$$

At full load;

$$\text{Back emf, } E_{bfl} = V_t - I_{afl} (R_a)$$

$$= 220 - 45 (0.5)$$

$$E_{b\ fl} = 197.5 \text{ V}$$

As flux is given constant;

then, we can write;  $E_b \propto N$

$$\text{or, } \frac{E_{b\ fl}}{E_{b0}} = \frac{N_{fl}}{N_0}$$

$$N_{fl} = \left( \frac{197.5}{218.5} \right) \times 1500 = 1355.83 \approx 1356 \text{ rpm}$$

29. (d)

Given:

S.C. Test (H.V): 57.5 V, 8.34 A, 284 W

$$Z_{eq} = \frac{57.5}{8.34} = 6.894 \ \Omega$$

$$R_{eq} = \frac{284}{(8.34)^2} = 4.083 \ \Omega$$

$$X_{eq} = \sqrt{Z_{eq}^2 - R_{eq}^2} = 5.555 \ \Omega$$

For voltage regulation to be zero;

$$\text{Power factor; } \cos \phi = \cos \tan^{-1} \left( \frac{R_{eq}}{X_{eq}} \right) = \cos (36.32^\circ)$$

$$\cos \phi = 0.805 \text{ leading}$$

30. (a)

Primary is star connected and secondary is delta connected.

$$(V_L)_{\text{primary}} = 11000 \text{ V}$$

$$(V_{\text{ph}})_{\text{primary}} = \frac{11000}{\sqrt{3}} \text{ V}$$

$$\frac{(V_{\text{ph}})_{\text{sec}}}{(V_{\text{ph}})_{\text{prim}}} = \frac{1}{5}$$

$$\therefore \text{Turns ratio} = \left( \frac{\text{High voltage}}{\text{Low voltage}} \right)_{\text{phase}}$$

$$\therefore (V_{\text{ph}})_{\text{sec}} = \frac{11000}{5\sqrt{3}} \text{ V}$$

$$(V_{\text{ph}})_{\Delta} = (V_L)_{\Delta}$$

$$\text{Output kVA} = \sqrt{3} V_L I_L$$

$$= \sqrt{3} \times \frac{11000}{5\sqrt{3}} \times 423 = 930.6 \text{ kVA}$$

